## Warranty For RIVA Residential Wall Hung Gas Boilers

FIRST 2 YEARS-WARRANTY FOR RIVA SERIES RESIDENTIAL HOT WATER BOILERS: QHT warrants that its wall hung boiler and casing are free from defects in material and workmanship for 2 years from the date of installation. If any part on the boiler is found to be defective within this period, QHT will replace the part free of charge.

FIRST 10 YEARS-WARRANTY FOR RIVA SERIES RESIDENTIAL HOT WATER BOILERS: Biasi warrants that the stainless steel heat exchanger of the RIVA boilers are free from defects in material and workmanship for 10 years from the date of installation. If the stainless steel heat exchanger is found to be defective within the first 10 years after installation, QHT and Biasi will replace the stainless steel heat exchanger.

These warranties are subject to the condition that a heating contractor whose principal occupation is the sale and installation of heating equipment must have installed the boiler. PARTS, WHICH ARE COVERED, consists of all materials supplied by Biasi, identified by QHT's part numbers in its literature. Other parts supplied by the installer carry their own warranty and each manufacturer has responsibility for its own products.

NOTE: ANY PART, WHICH IS REPLACED UNDER WARRANTY, CARRIES ONLY THE UNEXPIRED PORTION OF THE ORIGINAL WARRANTY.

## OWNER RESPONSIBILITIES:

- Provide for proper installation, which includes pressure relief and pressure reducing valves and high limit safety controls on closed systems.
- Provide qualified periodic service to prolong proper operation and service.
- Insure that boiler is installed in accordance with all codes and ordinances.
- This warranty does not apply to boilers, which are subject to misuse, abuse, neglect, alteration, accident, excessive temperature, excessive pressure, or corrosive water or atmosphere.
- Owner will be responsible for return of faulty components to Portsmouth, NH, freight pre-paid.

QHT and Biasi will not be responsible for:

- Components that are part of the heating system, but were not manufactured by Biasi or QHT as part of the boiler.
- The workmanship of the installers of RIVA boilers. Furthermore, this warranty does not assume any liability for unsatisfactory performance caused by improper installation.
- Any costs for labor to remove or replace the faulty component.
- 4. Improper boiler application or adjustments, control settings, care or maintenance.
- Any damage associated with corrosion or leakage due to the use of "non-barrier", plastic pipe in the heating system.

\*IMPLIED WARRANTIES OF FITNESS FOR A PARTICULAR PURPOSE AND MERCHANTABILITY SHALL BE LIMITED TO THE DURATION OF THE EXPRESSED WARRANTY. BIASI AND QHT EXPRESSLY DISCLAIM AND EXCLUDE ANY LIABILITY FOR CONSEQUENTIAL OR INCIDENTAL DAMAGES FOR BREACH OF ANY EXPRESSED OR IMPLIED WARRANTY.

THIS WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS, AND YOU MAY HAVE OTHER RIGHTS THAT VARY FROM STATE TO STATE.

For prompt warranty service, notify the installer, who, in turn, will notify the distributor from whom the boiler was purchased. If this does not result in corrective action, contact Biasi through Quincy Hydronic Technology (Address Below) with details in support of the warranty claim. All claims must be processed through proper trade channels. Contact with Biasi directly is not recommended for rapid claim settlement.

Quincy Hydronic Technology Inc., 3560 Lafayette Road, Bldg. 2, Unit A Portsmouth, NH, 03801 Tel. (603) 334-6400

## **BIASI BOILER WARRANTY REGISTRATION**

IMPORTANT., Registration required. To gain complete warranty Protection, fill in and mail this card, within 1 year of installation to the address listed below

NAME:		ADDRESS:
CITY:	STATE:	ZIP:
BOILER SERIAL NO.:		DATE OF INSTALL:
NAME OF INSTALL CO .:		ADDRESS:
CITY:	STATE:	ZIP:
RETURN TO: QHT, INC., 3560 Lafayette Road, Bldg. 2 Unit A, PORTSMOUTH, NH 03801		